




Item	Qty.	Description
1	1	38”h Q918 Vertical Extrusion
2	1	38”h Q918 Vertical Extrusion
3	1	38”h Q918 Vertical Extrusion
4	1	38”h Q918 Vertical Extrusion
5	1	38”h Q918 Vertical Extrusion
6	1	38”h Q918 Vertical Extrusion
7	1	32.155”w Z45 Horizontal Extrusion
8	1	32.155”w Z45 Horizontal Extrusion
9	1	32.155”w Z45 Horizontal Extrusion
10	1	32.155”w Z45 Horizontal Extrusion
11	1	15”w Z45 Horizontal Extrusion
12	1	15”w Z45 Horizontal Extrusion
13	1	15”w Z45 Horizontal Extrusion
14	1	15”w Z45 Horizontal Extrusion
15	1	15”w Z45 Horizontal Extrusion
16	1	15”w Z45 Horizontal Extrusion
17	1	32.155”w Z45 Horizontal Extrusion
18	1	32.155”w Z45 Horizontal Extrusion
19	1	32.155”w Z45 Horizontal Extrusion
20	1	32.155”w Z45 Horizontal Extrusion
--	2	Door
--	6	18”h Shelf Supports


- Steps:
- 1) Assemble lower horizontals [7,9,11,13,15,17,19] between verticals [1,2,3,4,5,6].
 - 2) Insert infills between verticals [1,2], [2,3], [3,4], [1,5].
 - 3) Connect upper horizontals [8,10,12,14,16,18,20] between verticals [1,2,3,4,5,6].
 - 4) Attach Doors between verticals [4,5], [5,6]. See Door Attachment detail.
 - 5) Affix shelf supports to inside of counter assembly using Velcro; place shelf onto shelf supports.
 - 6) Affix Sintra Panels to outside of assembly, using Velcro.
 - 6) Attach Counter Top to top of assembly.



When assembled



BACK VIEW



FRONT VIEW

SETUP INSTRUCTIONS

General Setup Instructions


- Read entire setup instruction manual prior to unpacking parts and pieces.
- The setup instructions are created specifically for this configuration.
- Setup instructions are laid out sequentially in steps, including exploded views with detailed explanation for assembly.

Cleaning & Packing


- For Cleaning Metal, Plex, & Laminate Parts:
Use a **MILD NON-ABRASIVE** cleanser and soft cloth/paper towel to clean all surfaces.
- Keep exhibit components away from heat and prolonged sun exposure.
Heat and UV exposure will warp and fade components.
- Retain all provided Packing Materials.
All provided packing materials are for ease of repacking & component protection.

Disassembly


- For loss prevention, tighten all set screws and locks during disassembly.




Hex Tool - Essential for Assembly




Part Identification - Numbering




Spline Connection



Base Plate & Extrusion Connection




Extrusion & Lock Connection



Engaged Lock



WARNING



DO NOT USE POWER TOOLS



LADDERS OR LIFTS
MAY BE REQUIRED



ALL CONNECTIONS MUST
BE TIGHTLY SECURED