







Item	Qty.	Description
1	1	40"h Q918 Vertical Extrusion
2	1	40"h Q918 Vertical Extrusion
3	1	48"h S44 Vertical Extrusion
4	1	40"h Q918 Vertical Extrusion
5/5A	1/1	19.25" Z45 curved Horizontal Extrusion
6/6A	1/1	8" Z45 curved Horizontal Extrusion
7/7A	1/1	19.25" Z45 curved Horizontal Extrusion

Steps

- 1) Attach lower Horizontals [5,6,7] between Verticals [1,2,3,4] as shown.
- 2) Insert Infills and secure with upper Horizontals [5A,6A,7A].
- 3) Place shelf on top of shelf pins.
- 4) Place counter top on top of assembled base.



SETUP INSTRUCTIONS

General Setup Instructions


- Read entire setup instruction manual prior to unpacking parts and pieces.
- The setup instructions are created specifically for this configuration.
- Setup instructions are laid out sequentially in steps, including exploded views with detailed explanation for assembly.

Cleaning & Packing


- For Cleaning Metal, Plex, & Laminate Parts: Use a **MILD NON-ABRASIVE** cleanser and soft cloth/paper towel to clean all surfaces.
- Keep exhibit components away from heat and prolonged sun exposure.
Heat and UV exposure will warp and fade components.
- Retain all provided Packing Materials. All provided packing materials are for ease of repacking & component protection.

Disassembly


- For loss prevention, tighten all set screws and locks during disassembly.




Hex Tool - Essential for Assembly




Part Identification - Numbering




Spline Connection



Base Plate & Extrusion Connection



Extrusion & Lock Connection




Engaged Lock



WARNING



DO NOT USE POWER TOOLS




LADDERS OR LIFTS
MAY BE REQUIRED




ALL CONNECTIONS MUST
BE TIGHTLY SECURED


Top View of Each Level




Level 1



Level 2



Level 3



Level 4